Tonelify

CHEAT SHEET

Mooer GE1000 Settings Cheat Sheet

Five amps on a 0 to 100 scale. Starting points.

	GAIN	BASS	MID	TREBLE	BRIGHTNESS
Clean 65 US TW NORMAL 6L6, SPRING	 30	 50	 50	 60	 50
Edge UK 30 OD 808 IN FRONT	 45	 45	 55	 60	 55
Classic rock J800 KEEP THE MIDS UP	 60	 50	 65	 60	 50
Metal TRI REC DS NOISE GATE FIRST	 65	 55	 40	 60	 50
Lead SLOW 100 DS DELAY ON CTRL	 65	 50	 60	 55	 50

TUNER	Hold A and B.
LOOPER	Hold B and C, then BANK down.
CTRL	Press the lit preset again.
POWER	Add Poweramp after a preamp.
SAVE	Press SAVE before you switch.
AI EQ	AI EQ Master in EQ, then play.